Zeitschrift:	IABSE congress report = Rapport du congrès AIPC = IVBH Kongressbericht	
Band:	12 (1984)	
Artikel:	Rehabilitation of post-tensioned bridge deck	
Autor:	Ostenfeld, Klaus H. / Jonsen, Leif	
DOI:	https://doi.org/10.5169/seals-12281	

Nutzungsbedingungen

Die ETH-Bibliothek ist die Anbieterin der digitalisierten Zeitschriften auf E-Periodica. Sie besitzt keine Urheberrechte an den Zeitschriften und ist nicht verantwortlich für deren Inhalte. Die Rechte liegen in der Regel bei den Herausgebern beziehungsweise den externen Rechteinhabern. Das Veröffentlichen von Bildern in Print- und Online-Publikationen sowie auf Social Media-Kanälen oder Webseiten ist nur mit vorheriger Genehmigung der Rechteinhaber erlaubt. <u>Mehr erfahren</u>

Conditions d'utilisation

L'ETH Library est le fournisseur des revues numérisées. Elle ne détient aucun droit d'auteur sur les revues et n'est pas responsable de leur contenu. En règle générale, les droits sont détenus par les éditeurs ou les détenteurs de droits externes. La reproduction d'images dans des publications imprimées ou en ligne ainsi que sur des canaux de médias sociaux ou des sites web n'est autorisée qu'avec l'accord préalable des détenteurs des droits. <u>En savoir plus</u>

Terms of use

The ETH Library is the provider of the digitised journals. It does not own any copyrights to the journals and is not responsible for their content. The rights usually lie with the publishers or the external rights holders. Publishing images in print and online publications, as well as on social media channels or websites, is only permitted with the prior consent of the rights holders. <u>Find out more</u>

Download PDF: 10.08.2025

ETH-Bibliothek Zürich, E-Periodica, https://www.e-periodica.ch

Rehabilitation of Post-Tensioned Bridge Deck

Klaus H. OSTENFELD	Leif JONSEN
Head of Bridge Dep.	Chief Bridge Eng.
Cowiconsult	Cowiconsult

Virum, Denmark

Virum, Denmark

The bridge was constructed in 1967 and hereafter regular routine inspections were carried out. In 1981 a major examination took place. Larger zones of deteriorated concrete were found in one of the cantilevered flanges, especially in areas near the abutments.

The bridge deck surface has a cross slope of 6% and consequently damage had only taken place in the lower cantilever, and fortunately not in the central part of the girder where the longitudinal main tendons are positioned. This distribution of the damage made repair possible. A full replacement of the superstructure would have resulted in an expenditure of more than 250% of the repair cost and almost total closure of one of the major motorways in Denmark.

The deterioration had started due to a leak in the waterproofing membrane. Unfortunately, the underneath concrete was not resistant against alkaline reactions.

- * - * - * - * - * -

After removal of the bridge deck pavement and water proofing, the deteriorated areas were surveyed by core drilling.

The deteriorated concrete was removed, however, in such a way that the reinforcement and prestressing tendons were not harmed. In this context it was very important that the transverse prestressing in the cantilevers could be reestablished. The transverse prestressing tendons consist of 12 dia. 5 mm wires. In order to protect these wires, the original sheath and grout were not removed until just before the new sheathing was ready to be installed. As it can be seen from the original transverse tendon arrangement, it was not possible to reuse the existing anchorages.

A new system was developed by Skandinavisk Spændbeton. A simple bar anchorage with thread and nut was connected to the wires. The details are shown on the poster. After casting the deck the wires were re-stressed and grouted.

Due to the repair work the longitudinal prestressing forces were lost in the cantilever. Consequently, it was necessary to place some additional ordinary reinforcement in the longitudinal direction, especially at the end of the bridge deck.

REHABILITATION OF POST-TENSIONED BRIDGE DECK

