# Railway bridges of corrosion resistant steel in Japan

Autor(en): Abe, Hidehiko / Sakamoto, Kenji

Objekttyp: Article

Zeitschrift: IABSE reports = Rapports AIPC = IVBH Berichte

Band (Jahr): **64 (1991)** 

PDF erstellt am: 23.09.2024

Persistenter Link: https://doi.org/10.5169/seals-49335

#### Nutzungsbedingungen

Die ETH-Bibliothek ist Anbieterin der digitalisierten Zeitschriften. Sie besitzt keine Urheberrechte an den Inhalten der Zeitschriften. Die Rechte liegen in der Regel bei den Herausgebern. Die auf der Plattform e-periodica veröffentlichten Dokumente stehen für nicht-kommerzielle Zwecke in Lehre und Forschung sowie für die private Nutzung frei zur Verfügung. Einzelne Dateien oder Ausdrucke aus diesem Angebot können zusammen mit diesen Nutzungsbedingungen und den korrekten Herkunftsbezeichnungen weitergegeben werden.

Das Veröffentlichen von Bildern in Print- und Online-Publikationen ist nur mit vorheriger Genehmigung der Rechteinhaber erlaubt. Die systematische Speicherung von Teilen des elektronischen Angebots auf anderen Servern bedarf ebenfalls des schriftlichen Einverständnisses der Rechteinhaber.

# Haftungsausschluss

Alle Angaben erfolgen ohne Gewähr für Vollständigkeit oder Richtigkeit. Es wird keine Haftung übernommen für Schäden durch die Verwendung von Informationen aus diesem Online-Angebot oder durch das Fehlen von Informationen. Dies gilt auch für Inhalte Dritter, die über dieses Angebot zugänglich sind.

Ein Dienst der *ETH-Bibliothek* ETH Zürich, Rämistrasse 101, 8092 Zürich, Schweiz, www.library.ethz.ch



# Railway Bridges of Corrosion Resistant Steel in Japan

Ponts ferroviaires en acier résistant à la corrosion au Japon Eisenbahnbrücken aus korrosionsbeständigem Stahl in Japan

#### Hidehiko ABE

Professor Univ. of Utsunomiya Utsunomiya, Japan

## Kenji SAKAMOTO

Senior Engineer Technical Inst. of Railways Tokyo, Japan

#### 1. INTRODUCTION

A considerable number of railway bridges have been constructed of corrosion resistant steel, so-called "weathering steel", without painting in these ten years



Photo 1. Third Okawa Bridge

in Japan (say, 70 sets of span and 11.742 tons in total). Some of them were furnished with test specimens for future observation. type of bridge has been applied to only an open type bridge, where structural members are well exposed to rainfall and located in rural areas where air is not polluted. Such conditions are favorable to formation of the stable patina, an anticorrosive surface layer, which is essential to the protection of steel from corrosion. At present, all the brides are

generally in a very satisfactory condition and prove to be successful.




Photo 2. Track structure

## 2. STRUCTURAL DETAILS

The structural details of the weathering steel bridges for railways in Japan are so modified, as to fit the use of weathering steel without painting. They have been carefully designed, so that water and dust staying on the structural members should be minimized as shown in Fig. 1. Such considerations will be useful also to ordinary painted bridges for better durability. In Third Okawa Bridge (Photo 1), for instance, 1) The upper surfaces of horizontal mem-

bers, even the flanges of stringer and




Fig.1. Examples of structural details

floor beam and chord members are inclined by 5%.

 Larger horizontal gusset plates are provided with large openings.

3) The chord members and the panel point portions are closed for air-tightness, except for their splice portions, the inside of which is coated with tar - epoxy

resin paint.

4) The rail track structure is different from an ordinary one with wood sleepers. Since the flange surface in contact with the sleepers is usually most severely damaged by corrosion, the rails are fastened to the flanges of the steel girders with a special device instead of wood ties as shown in Photo 2. It is drastically effective in reduction of maintenance work for the track as well as the bridge structure. And

5) The edge of the upper side of concrete pier is raised and water is gathered to the drain pipe, so that rainwater washing the bridge may not stain the flank of pier, as

seen in Photo 1.

#### EXAMPLE OF OBSERVATION

Five years after Third Okawa Bridge was erected and opened to traffic, the bridge structure and the test specimens installed nearby were closely examined, by the visual inspection, X-ray test, Ferroxyl test, etc. In addition, some bolts used in the bridge were removed to see the state of bolts themselves and the inside of bolt holes. The summary of the results is as follows; 1) As a whole, the condition is so good, that reduction in the plate thickness can not be measured.2) According to Ferroxyl test on various parts of the bridge and X-ray test on the exposed specimens, the stable patina has been better formed on the surface has been directly exposed to rain-fall and dried immediately. From this of view, the upper surface is most favorable, if water does not stay, and followed by the vertical surface on a sunny side. In case water is apt to stay on horizontal surface, however, the patina is not easily formed. On the surface of underside, the patina is seldom formed and slight corrosion pits are recognized, the rate of corrsion is very slow if the environmental atmosphere is not humid, and 3) Some of the bolt holes were filled with water. Though it has resulted in no appreciable detrimental effect as yet, it may cause the corrosion of the bolts in the future. It will, therefore, be necessary to keep them water-tight.