Aerodynamic stability of long-span box girder

- Autor(en): Tanaka, A. / Miyashita, C. / Nomura, N.
- Objekttyp: Article
- Zeitschrift: IABSE congress report = Rapport du congrès AIPC = IVBH Kongressbericht

Band (Jahr): 12 (1984)

PDF erstellt am: **21.09.2024**

Persistenter Link: https://doi.org/10.5169/seals-12247

Nutzungsbedingungen

Die ETH-Bibliothek ist Anbieterin der digitalisierten Zeitschriften. Sie besitzt keine Urheberrechte an den Inhalten der Zeitschriften. Die Rechte liegen in der Regel bei den Herausgebern. Die auf der Plattform e-periodica veröffentlichten Dokumente stehen für nicht-kommerzielle Zwecke in Lehre und Forschung sowie für die private Nutzung frei zur Verfügung. Einzelne Dateien oder Ausdrucke aus diesem Angebot können zusammen mit diesen Nutzungsbedingungen und den korrekten Herkunftsbezeichnungen weitergegeben werden.

Das Veröffentlichen von Bildern in Print- und Online-Publikationen ist nur mit vorheriger Genehmigung der Rechteinhaber erlaubt. Die systematische Speicherung von Teilen des elektronischen Angebots auf anderen Servern bedarf ebenfalls des schriftlichen Einverständnisses der Rechteinhaber.

Haftungsausschluss

Alle Angaben erfolgen ohne Gewähr für Vollständigkeit oder Richtigkeit. Es wird keine Haftung übernommen für Schäden durch die Verwendung von Informationen aus diesem Online-Angebot oder durch das Fehlen von Informationen. Dies gilt auch für Inhalte Dritter, die über dieses Angebot zugänglich sind.

Ein Dienst der *ETH-Bibliothek* ETH Zürich, Rämistrasse 101, 8092 Zürich, Schweiz, www.library.ethz.ch

http://www.e-periodica.ch

AERODYNAMIC STABILITY OF LONG-SPAN BOX GIRDER

Tozaki Bridge is the north approach to Ohnaruto Br. reach to Onnaruto Br. Ispension bridge) of Kobe-Na ito Route, Honshu - Shikoku idge Project, Japan. Daili Bridge is 2 sets of conti-rous box girders and has slen-And the set of the set





Fig-2 Response of original section (without topography)

The original section was suspected to have unstable aerodynamic behavior, so, wind tunnel tests were conducted to reveal that the original section had vortex-induced oscillation at the wind speed of 15 to 20 m/s and galloping which should not oc-cur below the speed of 92 m/s (10minutes average), the dy-namic design wind speed. Various stabilizers and their effects were tested in wind tunnels.

As the results of a series of wind tunnel testings, the final sta-bilizers were determined as follows: Double flaps were attached to the whole length of the bridge in order to restrict the amplitude of vortex-induced oscillation tess than 200 mm (7/B=0.01) which was the allowable value from the viewpoint of fatigue and runnability of automobiles. And, intermittent lower skirts to suppress galloping which might destroy the bridge in a short time if it appeared were provid-ed to the 4-spans continuous girder. After the completion of the bridge in the summer of 1983, os-cillation and wind have been observed, but no considerable oscil-lation has been generated so far. because no strong wind be-yond 20 m/s has unfortunately blown.

1.009.5



1098