Zeitschrift:	IABSE reports = Rapports AIPC = IVBH Berichte
Band:	60 (1990)
Artikel:	In situ investigations on soil anchors
Autor:	Derveaux, Godfried / Tousseyn, Luc / [s.n.]
DOI:	https://doi.org/10.5169/seals-46571

Nutzungsbedingungen

Die ETH-Bibliothek ist die Anbieterin der digitalisierten Zeitschriften auf E-Periodica. Sie besitzt keine Urheberrechte an den Zeitschriften und ist nicht verantwortlich für deren Inhalte. Die Rechte liegen in der Regel bei den Herausgebern beziehungsweise den externen Rechteinhabern. Das Veröffentlichen von Bildern in Print- und Online-Publikationen sowie auf Social Media-Kanälen oder Webseiten ist nur mit vorheriger Genehmigung der Rechteinhaber erlaubt. <u>Mehr erfahren</u>

Conditions d'utilisation

L'ETH Library est le fournisseur des revues numérisées. Elle ne détient aucun droit d'auteur sur les revues et n'est pas responsable de leur contenu. En règle générale, les droits sont détenus par les éditeurs ou les détenteurs de droits externes. La reproduction d'images dans des publications imprimées ou en ligne ainsi que sur des canaux de médias sociaux ou des sites web n'est autorisée qu'avec l'accord préalable des détenteurs des droits. <u>En savoir plus</u>

Terms of use

The ETH Library is the provider of the digitised journals. It does not own any copyrights to the journals and is not responsible for their content. The rights usually lie with the publishers or the external rights holders. Publishing images in print and online publications, as well as on social media channels or websites, is only permitted with the prior consent of the rights holders. <u>Find out more</u>

Download PDF: 08.08.2025

ETH-Bibliothek Zürich, E-Periodica, https://www.e-periodica.ch

Examen in situ de bêches d'ancrage

In Situ Untersuchung von Grundarkern

Godfried DERVEAUX

Man. Dir. Ingenieursbureau Gent, Belgium

Luc TOUSSEYN

Project Mgr Ingenieursbureau Gent, Belgium

On the occasion of an important tunnelling project in Belgium (Liefkenshoektunnel, Antwerpen), a building excavation has been carried out with an anchored steel sheet piling. The wall anchorage is realized by means of steel soil anchors with tendons. In order to do some tests in situ, three of the steel soil anchors are replaced by GRP soil anchors. The construction is of a temporary nature (about 18 months). The lab tests turned out to be very promising. The in situ investigations will be continued until the end of 1990. However, the first results prove to be very promising.

2. PROPERTIES OF THE ANCHORS

The soil anchors consist of 15 mm or 10 mm GRP rods made of glass fibre reinforced vinylester.

2.1. Test anchors in lab

Pull tests were carried out on two different types of anchors, i.e. :

- 1 anchor consisting of 19 x 10 mm rods;



a purpose-made anchor head. This required a special mixture of resin and fillers. The test anchors were about 3.50 m long. In the middle of the free rod length some strain gages were applied (see fig. 1).

The rods were anchored in

The tensile force was gradually increased; at a loading rate of approximately 50 kN per minute. Each loading step was followed by a pause of about three minutes. When a total load of 600 kN had been achieved, a 15 minutes' pause was introduced.

The first test has been carried out on the 12-rods system, the second test on the 19-rods system. The load-deformation diagrams are shown in fig. 2 and fig. 3.



2.2.Test anchors in situ

high pressure) grouting (see fig. 4).

The fabricated anchors are of the same type as those described in
2.1 : - 1 anchor of 19 10-mm rods;
 - 1 anchor of 12 15-mm rods;
 - 1 anchor of 3 15-mm rods + 16 10-mm rods.
The anchors are to withstand a useful tensile force of 570 kN
(see fig. 4). Soil anchorage is realized by means of VHP (very



The anchors have been placed in the beginning of May 1989 and tightened at the end of the month. They have been tightened up to 1.5 times the service load and fixed at 1 time the service load. Early January 1990, one anchor has been checked and a remaining tensile force of 600 kN has been measured ! When increasing the force to 1,130 kN, the anchor did not fail (the theoretical maximum value is 1,200 kN). So, this first result means there has been no degradation in strength of the anchors. Further results will be available by mid 1990.