Zeitschrift: IABSE reports = Rapports AIPC = IVBH Berichte

Band: 77 (1998)

Inhaltsverzeichnis

Nutzungsbedingungen

Die ETH-Bibliothek ist die Anbieterin der digitalisierten Zeitschriften auf E-Periodica. Sie besitzt keine Urheberrechte an den Zeitschriften und ist nicht verantwortlich für deren Inhalte. Die Rechte liegen in der Regel bei den Herausgebern beziehungsweise den externen Rechteinhabern. Das Veröffentlichen von Bildern in Print- und Online-Publikationen sowie auf Social Media-Kanälen oder Webseiten ist nur mit vorheriger Genehmigung der Rechteinhaber erlaubt. Mehr erfahren

Conditions d'utilisation

L'ETH Library est le fournisseur des revues numérisées. Elle ne détient aucun droit d'auteur sur les revues et n'est pas responsable de leur contenu. En règle générale, les droits sont détenus par les éditeurs ou les détenteurs de droits externes. La reproduction d'images dans des publications imprimées ou en ligne ainsi que sur des canaux de médias sociaux ou des sites web n'est autorisée qu'avec l'accord préalable des détenteurs des droits. En savoir plus

Terms of use

The ETH Library is the provider of the digitised journals. It does not own any copyrights to the journals and is not responsible for their content. The rights usually lie with the publishers or the external rights holders. Publishing images in print and online publications, as well as on social media channels or websites, is only permitted with the prior consent of the rights holders. Find out more

Download PDF: 10.12.2025

ETH-Bibliothek Zürich, E-Periodica, https://www.e-periodica.ch



Table of Contents

Preface	3
Table of Contents	4
List of Authors	12
Keynote Lectures	16
DO VALLE Panel Buildings, Precast or Conventional Low Cost Buildings - Brazilian Experience and Reality	16
ZABEGAYEV, ALEXEYEV Modern Building Activities in the Region of Moscow: Problems and Solutions	18
Session 1 Evaluation of Deterioration of Buildings	20
KLOFT, WÖRNER Investigations of Mass Flow in the Existing Building Stock	20
ZIELINSKI, KOWALEWSKI Monitoring of Apartment Buildings	22
VIMMR Diagnoses of Large Panel Buildings in the Czech Republic	24
TROCKA Evaluation of Deterioration of Rural Buildings in Poland	26
BUCHER, ZABEL Dynamic in Situ Tests on a Damaged Historical Building	28
VAN GEMERT, VENDERICKX Evaluation of Resistivity Measurement of Masonry by Numerical Simulation	30
BARSAN, DINSOREANU Modal System Identification Technique in Structural Damage Assessment	32
ROCA Inspection of Concrete Floor Slabs by Means of Dynamic Test	34
GARCIA, GUTIÉRREZ, RODRIGUEZ Mechanical Properties and Bond Behaviour of Corroded Deformed Bars	36
MARQUARDT Locating Rebar Corrosion in Concrete Walls by Potential Measurements	38



BAYER, GATTERMAYEROVA, KRAL Dynamic Tests and Verification of Mechanical Properties of a Panel Building	40
SIGMUND, HERMAN Dynamic Characteristics as Indicator of Structural Integrity	42
AJDUKIEWICZ, KLISZCZEWICZ, MACKOWSKI Evaluation Prior to Repair of Industrial Reinforced Concrete Structures	44
CAPOZUCCA, CERRI Evaluation of the Behaviour of Corroded Beams	46
KUBICA, PAJAK, STAROSOLSKI Repair of a Swimming Pool after Design Errors	48
Session 2 Structural Safety and Durability of Existing Buildings	50
BOB Deterioration of Reinforced Concrete Structures under Normal Conditions	50
VAN GEMERT, SCHUEREMANS Reliability Analysis in Structural Masonry Engineering	52
TANNER Reliability-Based Evaluation Concept for Everyday Use	54
CRISTEA Nondeterministic Assessment of the Structural Performance	56
SPAETHE Evaluation of the Load-Carrying Capacity of Structural Members in Existing Buildings by Proof Load Testing	58
WITZANY Assessment of Structural Safety of Prefabricated Buildings	60
BLOCK Causes of Failures and Methods for Repair of Weather Panels	62
MIEDZIALOWSKI, MALESZA Long-Term Behaviour of Reinforced Concrete Panel Walls	64
WICHTOWSKI, CZAJKOWSKI Fatigue Life of Railway Bridge Welded Joints	66
MATTILA, PENTTI, LINDBERG Condition Investigation Prior to Renovation Process – A Systematic Approach	68
POPAESCU, SVEICA Durability Assessment of Prestressed Concrete Buildings in Bucharest	70



SCISLEWSKI, WOJTOWICZ Durability of Protecting Layers on Steel Cladding Sheets	72
AJDUKIEWICZ, HULIMKA, KLISZCZEWICZ Repairing and Extending the Lifespan of Chimney under Severe Conditions	74
Session 3 Cost Analysis and Planning	76
RADUJKOVIC, PEJOVIC Building Construction and Maintenance in Croatia	76
MILEWSKA, SZKLENNIK Humanisation and Modernisation of Substandard Housing Estates	78
HOLFELD Prefabricated Housing and Colours	80
KALLIO Production and Action Oriented Model for Renovation Projects	82
RIETZ Cost-Effective Modernisation of Housing in Panel Structures	84
KISSOMLYOI, SOMOGYI Saving and Restoring Technical Documents of Large Panel Buildings in Hungary	86
JARSKY Planning and Management of the Reconstruction of Historical Buildings	88
URMERSBACH, IHLENFELD, ENGELBRECHT Standardised Specifications Handbook for Prefabricated Block Buildings	90
MIRKOVIC, SNELER Rehabilitation of Recent Multiapartment Houses in Croatia	92
IZETBEGOVIC, ADAMOVIC, LINARIC Roof Repair in Croatia Applying Modern Technologies	94
MOGA, POPA Strategic Decisions about Rehabilitation of Buildings	96
POGORELOV, OLKHOVOY Methods of Reconstruction of Standard Five-storey Built-up Areas	98
KRIVOSHEEV Improvement of Operating Buildings and Structures in Ukraine	100



Session 4 Materials and Technology	102
TÄLJSTEN Strengthening of Building Structures with FRP-Fabrics	102
KOTYNIA, KAMINSKA Tests of Reinforced Concrete Strengthened with CFRP Plates	104
KUCHLER Renovation of Facades and Masonry with special Dry-Mix-Mortars	106
LAEFER Masonry Repair - The State of American Practice	108
BOLTE, BOETTGER Long-Term Stability of Joint Repairs in Building Construction	110
MLECNIK Recyclable Housing: The Challenge lies in Design	112
DOMSA, IORDACHESCU Saving Buildings by Relocation	114
BUYLE-BODIN, ZAHARIEVA, COURTIAL Recycling of Building Wastes – A Real Perspective for Bulgaria	116
LAEFER Replacement of Masonry – Important Selection Considerations	118
HAASIS Strengthening of Structures with Carbon Fibre Strips	120
LA TEGOLA, MANNI, NOVIELLO Flexural Reinforcement of Concrete Beams using FRP Plates	122
BOKAN-BOSILJKOV, ZARNIC, GOSTIC, BERGANT Strengthening of Bending Concrete Elements with Epoxy-Bonded Plates	124
KOSINSKA Strengthening Beams in the Shear Zone	126
STOROJENKO, TARANOVSKY, YERMOLENKO Reconstruction of Buildings with Concrete Filled Steel Tubes	128
BOB Some Procedures for Concrete Rehabilitation	130
TARANU, STRATEANU, ISOPESCU Structural Rehabilitation of an Industrial Steel Building	132
KHOMENKO Repair and Modernisation of Butt Joints in Enclosing Constructions	134



Use of Basaltic Fibers in Concrete and Thermal Insulation	136
Session 5 Repair and Rehabilitation Methods of Panel Buildings	138
HILLEMEIER Panel Buildings Torn between Demolition and Rehabilitation	138
BORLENGHI, FIORI, PAVESI, POLI, TRIVELLI Rehabilitation Methods for Residential Buildings	140
STEGER Upgrading of Residential Buildings in Precast Construction	142
ALEXANDRIAN Modernisation and Strengthening of Large-Panel Building	144
SCHEIDGES Renovation of Prefabricated Concrete Elements: Nikolaiviertel in Berlin	146
FOUAD Rehabilitation of Sandwich Wall Panels in the New German Federal States	148
SCISLEWSKI, WOJTOWICZ Repair of Concrete Sandwich Walls Fasteners and Layers in Residential Buildings	150
MOEGENBURG Refurbishment of Buildings with Back Ventilated Rainscreen Cladding	152
POHL Ventilated Cavity Façade System with Pre-painted Aluminium Sheet	154
REINWARTH Fastening Systems for Suspended Rear Ventilated Facades	156
GILYEN Retrofitting of Residential Prefabricated Buildings in Hungary	158
CRAMER, STAROSOLSKI, DZIERZEWICZ Sandwich-Systems in Poland in the Years 1970–1985	160
MOLA Analysis and Repair of Damages in Precast Reinforced Concrete Panels	162
MÜSSIG Self-Supporting Structures for the Restoration of Balconies	164



Operation C	
Session 6 Repair and Rehabilitation Methods of Historical Buildings	166
SOFRONIE Innovative Method for Repairing Masonry Buildings	166
GÜNTER, MÜLLER, HILSDORF Investigation and Repair of Old Culturally Valuable Concrete Structures	168
PAPIC, KLECINA, GULJAS Evaluation and Preservation of Historic Buildings in Osijek	170
MANDARA, MAZZOLANI Confining of Masonry Walls with Steel Elements	172
GROMYSZ Repairs of Vertically Deflected Buildings	174
PAKVOR, MURAVLJOV Damages and Rehabilitation of the Orthodox Cathedral in Belgrade	176
KAMINSKA, CZKWIANIANC, KOZICKI Reconstruction of Wooden Floors in 19th Century Industrial Buildings	178
VAN DER LINDEN, BLASS, SCHLAGER Timber Floors Strengthened with Concrete	180
GODYCKI-CWIRKO, PAWLICA Construction and Design of Composite Concrete-Timber Floors	182
SIGMUND, GULJAS, KLECINA In-plane Stiffness of the Prussic Caps	184
POPA Consolidation Works for a Historic Building	186
TAKAC, ZAGAR Roof Structure Renewal of the St. Peter and Paul Church in Osijek	188
ZEC The Dynamic Buffer Zone System	190
DREYER, HECHT Injection Methods for Retrofitting of Moisture Damaged Constructions	192
LOKOSEK, SIMUNIC BURSIC Consolidation of the Church of St. Mihajlo near Ston	194
PAJAK, SLUSAREK, KUBICA Preservation of the State Oswiecim-Brzezinka Museum	196
PAJAK, KUBICA, STAROSOLSKI Repairs of Coal Processing Buildings under Continuing Production	198



BOSNJAK-KLECINA, HERMAN, SIGMUND Stress Analysis in Masonry Arch Structures	200
Session 7 Energy Saving and Building Physics	202
STERNOVA Upgrading of Panel-Built Residential Houses	202
CZIESIELSKI Mold Fungus Formation in Large Panel Buildings and Subsequent Thermal Insulation	204
DREYER Thermal Protection and Moisture Proofing of Exterior Walls of Existing Buildings	206
KARIMIES, LEHTINEN, KETTUNEN, YRJÖLÄ Rain Screen Cladding Based on Steel Structures	208
VOGDT Rehabilitation of Large Panel Buildings using ETICS	210
GRZESZCZYK, WITCZAK Saving of Sacral Stained-Glass Window against Moisture Condensation	212
SIJANEC ZAVRL, GRUDEN Concept of Energy Restoration of Residential Buildings in Slovenia	214
CURTH Fully Automatic, Decentralised Ventilation System with Heat Recovery	216
TENNHARDT Complex Room Acoustics Analysis Methodology for Large Lecture Theatres	218
MARQUARDT Rehabilitation of Concrete Walls using Thermal Insulation	220
KASPER, KÄSER Mineral-Wool Based, Glased Curtain Walling with Solar Energy Use	222
ANDREICA, COMSA, RUS Influence of Glass Paned Areas on the Closing Walls of Buildings	224
SIJANEC ZAVRL, MALOVRH, ZUPAN Energy Audits of Schools in the Town of Kamnik	226
Session 8 Assessment and Rehabilitation of Existing Buildings after Accidents	228
CRAINIC Seismic Rehabilitation of Existing Buildings in Romania	228



CROCI, BONCI War and Earthquake in Dubrovnik: Preventive and Remedial Measures	230
REEVES Load Testing of Large Panel System Dwellings	232
ZARNIC, BAUMGARTNER, BOSILJKOV Strengthening of Buildings according to Eurocode 8 and National Standards	234
SANDI Saving Buildings under Conditions of High Seismic Risk	236
DORKA, FLYGARE Earthquake Retrofit of Large Panel Buildings by Basement Isolation	238
DRITSOS, VANDOROS, TAYLOR Retrofitting of Reinforced Concrete Frame Buildings	240
CIONI, CROCE, SALVATORE Damage of Reinforced Concrete Structures Exposed to Violent Thermal Gradient	242
BUCUR, CHIVU, ARDELEA Repair and Rehabilitation – Three Case Studies in Bucharest	244
MARKOV, KOKOSHUEV, MARKOVA Analysis of Deterioration of Civil Buildings in South Ukraine	246
ANASTASESCU, GADEA Antiseismic Protection and Rehabilitation of Buildings in Timisoara	248
STRUFE Emergency Protection of War Damaged Buildings	250
KAWULOK Protection of Church Buildings on Mining Areas	252
SIECZKOWSKI, BIELAWSKI, DMOCHOWSKI Reinforcement of Apartment Buildings Exposed to Paraseismic Tremors	254
CATARIG, KOPENETZ, ALEXA Structural Assessment and Strengthening of Existing Buildings	256
SANDI, STANCU A Case Study on a Historical Monument and Methodological Implications	258
IABSE REPORTS - RAPPORTS AIPC - IVBH BERICHTE	260
CD-ROM Reference Numbers	266