

**Zeitschrift:** IABSE reports = Rapports AIPC = IVBH Berichte  
**Band:** 77 (1998)

## **Inhaltsverzeichnis**

### **Nutzungsbedingungen**

Die ETH-Bibliothek ist die Anbieterin der digitalisierten Zeitschriften auf E-Periodica. Sie besitzt keine Urheberrechte an den Zeitschriften und ist nicht verantwortlich für deren Inhalte. Die Rechte liegen in der Regel bei den Herausgebern beziehungsweise den externen Rechteinhabern. Das Veröffentlichen von Bildern in Print- und Online-Publikationen sowie auf Social Media-Kanälen oder Webseiten ist nur mit vorheriger Genehmigung der Rechteinhaber erlaubt. [Mehr erfahren](#)

### **Conditions d'utilisation**

L'ETH Library est le fournisseur des revues numérisées. Elle ne détient aucun droit d'auteur sur les revues et n'est pas responsable de leur contenu. En règle générale, les droits sont détenus par les éditeurs ou les détenteurs de droits externes. La reproduction d'images dans des publications imprimées ou en ligne ainsi que sur des canaux de médias sociaux ou des sites web n'est autorisée qu'avec l'accord préalable des détenteurs des droits. [En savoir plus](#)

### **Terms of use**

The ETH Library is the provider of the digitised journals. It does not own any copyrights to the journals and is not responsible for their content. The rights usually lie with the publishers or the external rights holders. Publishing images in print and online publications, as well as on social media channels or websites, is only permitted with the prior consent of the rights holders. [Find out more](#)

**Download PDF:** 06.02.2026

**ETH-Bibliothek Zürich, E-Periodica, <https://www.e-periodica.ch>**



## Table of Contents

Preface	3
Table of Contents	4
List of Authors	12
<b>Keynote Lectures</b>	<b>16</b>
DO VALLE	
Panel Buildings, Precast or Conventional Low Cost Buildings – Brazilian Experience and Reality	16
ZABEGAYEV, ALEXEYEV	
Modern Building Activities in the Region of Moscow: Problems and Solutions	18
<b>Session 1</b>	
<b>Evaluation of Deterioration of Buildings</b>	<b>20</b>
KLOFT, WÖRNER	
Investigations of Mass Flow in the Existing Building Stock	20
ZIELINSKI, KOWALEWSKI	
Monitoring of Apartment Buildings	22
VIMMR	
Diagnoses of Large Panel Buildings in the Czech Republic	24
TROCKA	
Evaluation of Deterioration of Rural Buildings in Poland	26
BUCHER, ZABEL	
Dynamic in Situ Tests on a Damaged Historical Building	28
VAN GEMERT, VENDERICKX	
Evaluation of Resistivity Measurement of Masonry by Numerical Simulation	30
BARSAN, DINSOREANU	
Modal System Identification Technique in Structural Damage Assessment	32
ROCA	
Inspection of Concrete Floor Slabs by Means of Dynamic Test	34
GARCIA, GUTIÉRREZ, RODRIGUEZ	
Mechanical Properties and Bond Behaviour of Corroded Deformed Bars	36
MARQUARDT	
Locating Rebar Corrosion in Concrete Walls by Potential Measurements	38



<b>BAYER, GATTERMAYEROVA, KRAL</b> Dynamic Tests and Verification of Mechanical Properties of a Panel Building	40
<b>SIGMUND, HERMAN</b> Dynamic Characteristics as Indicator of Structural Integrity	42
<b>AJDUKIEWICZ, KLISZCZEWICZ, MACKOWSKI</b> Evaluation Prior to Repair of Industrial Reinforced Concrete Structures	44
<b>CAPOZUCCA, CERRI</b> Evaluation of the Behaviour of Corroded Beams	46
<b>KUBICA, PAJAK, STAROSOLSKI</b> Repair of a Swimming Pool after Design Errors	48
<b>Session 2</b> <b>Structural Safety and Durability of Existing Buildings</b>	50
<b>BOB</b> Deterioration of Reinforced Concrete Structures under Normal Conditions	50
<b>VAN GEMERT, SCHUEREMANS</b> Reliability Analysis in Structural Masonry Engineering	52
<b>TANNER</b> Reliability-Based Evaluation Concept for Everyday Use	54
<b>CRISTEA</b> Nondeterministic Assessment of the Structural Performance	56
<b>SPAETHE</b> Evaluation of the Load-Carrying Capacity of Structural Members in Existing Buildings by Proof Load Testing	58
<b>WITZANY</b> Assessment of Structural Safety of Prefabricated Buildings	60
<b>BLOCK</b> Causes of Failures and Methods for Repair of Weather Panels	62
<b>MIEDZIALOWSKI, MALESZA</b> Long-Term Behaviour of Reinforced Concrete Panel Walls	64
<b>WICHTOWSKI, CZAJKOWSKI</b> Fatigue Life of Railway Bridge Welded Joints	66
<b>MATTILA, PENTTI, LINDBERG</b> Condition Investigation Prior to Renovation Process – A Systematic Approach	68
<b>POPAESCU, SVEICA</b> Durability Assessment of Prestressed Concrete Buildings in Bucharest	70



SCISLEWSKI, WOJTOWICZ Durability of Protecting Layers on Steel Cladding Sheets	72
AJDUKIEWICZ, HULIMKA, KLISZCZEWICZ Repairing and Extending the Lifespan of Chimney under Severe Conditions	74
<b>Session 3</b> <b>Cost Analysis and Planning</b>	76
RADUJKOVIC, PEJOVIC Building Construction and Maintenance in Croatia	76
MILEWSKA, SZKLENNIK Humanisation and Modernisation of Substandard Housing Estates	78
HOLFELD Prefabricated Housing and Colours	80
KALLIO Production and Action Oriented Model for Renovation Projects	82
RIETZ Cost-Effective Modernisation of Housing in Panel Structures	84
KISSOMLYOI, SOMOGYI Saving and Restoring Technical Documents of Large Panel Buildings in Hungary	86
JARSKY Planning and Management of the Reconstruction of Historical Buildings	88
URMERSBACH, IHLENFELD, ENGELBRECHT Standardised Specifications Handbook for Prefabricated Block Buildings	90
MIRKOVIC, SNELER Rehabilitation of Recent Multiapartment Houses in Croatia	92
IZETBEGOVIC, ADAMOVIC, LINARIC Roof Repair in Croatia Applying Modern Technologies	94
MOGA, POPA Strategic Decisions about Rehabilitation of Buildings	96
POGORELOV, OLKHOVOY Methods of Reconstruction of Standard Five-storey Built-up Areas	98
KRIVOSHEEV Improvement of Operating Buildings and Structures in Ukraine	100



<b>Session 4</b>	
<b>Materials and Technology</b>	<b>102</b>
<b>TÄLJSTEN</b>	
Strengthening of Building Structures with FRP-Fabrics	102
<b>KOTYNIA, KAMINSKA</b>	
Tests of Reinforced Concrete Strengthened with CFRP Plates	104
<b>KUCHLER</b>	
Renovation of Facades and Masonry with special Dry-Mix-Mortars	106
<b>LAEFER</b>	
Masonry Repair – The State of American Practice	108
<b>BOLTE, BOETTGER</b>	
Long-Term Stability of Joint Repairs in Building Construction	110
<b>MLECNIK</b>	
Recyclable Housing: The Challenge lies in Design	112
<b>DOMSA, IORDACHESCU</b>	
Saving Buildings by Relocation	114
<b>BUYLE-BODIN, ZAHARIEVA, COURTIAL</b>	
Recycling of Building Wastes – A Real Perspective for Bulgaria	116
<b>LAEFER</b>	
Replacement of Masonry – Important Selection Considerations	118
<b>HAASIS</b>	
Strengthening of Structures with Carbon Fibre Strips	120
<b>LA TEGOLA, MANNI, NOVIELLO</b>	
Flexural Reinforcement of Concrete Beams using FRP Plates	122
<b>BOKAN-BOSILJKOV, ZARNIC, GOSTIC, BERGANT</b>	
Strengthening of Bending Concrete Elements with Epoxy-Bonded Plates	124
<b>KOSINSKA</b>	
Strengthening Beams in the Shear Zone	126
<b>STOROJENKO, TARANOVSKY, YERMOLENKO</b>	
Reconstruction of Buildings with Concrete Filled Steel Tubes	128
<b>BOB</b>	
Some Procedures for Concrete Rehabilitation	130
<b>TARANU, STRATEANU, ISOPESCU</b>	
Structural Rehabilitation of an Industrial Steel Building	132
<b>KHOMENKO</b>	
Repair and Modernisation of Butt Joints in Enclosing Constructions	134



LESHAVA, TSITSILASHVILI, GIGINEISHVILI Use of Basaltic Fibers in Concrete and Thermal Insulation	136
<b>Session 5</b>	
<b>Repair and Rehabilitation Methods of Panel Buildings</b>	138
HILLEMEIER Panel Buildings Torn between Demolition and Rehabilitation	138
BORLENGHI, FIORI, PAVESI, POLI, TRIVELLI Rehabilitation Methods for Residential Buildings	140
STEGER Upgrading of Residential Buildings in Precast Construction	142
ALEXANDRIAN Modernisation and Strengthening of Large-Panel Building	144
SCHEIDGES Renovation of Prefabricated Concrete Elements: Nikolaiviertel in Berlin	146
FOUAD Rehabilitation of Sandwich Wall Panels in the New German Federal States	148
SCISLEWSKI, WOJTOWICZ Repair of Concrete Sandwich Walls Fasteners and Layers in Residential Buildings	150
MOEGENBURG Refurbishment of Buildings with Back Ventilated Rainscreen Cladding	152
POHL Ventilated Cavity Façade System with Pre-painted Aluminium Sheet	154
REINWARTH Fastening Systems for Suspended Rear Ventilated Facades	156
GILYEN Retrofitting of Residential Prefabricated Buildings in Hungary	158
CRAMER, STAROSOLSKI, DZIERZEWICZ Sandwich-Systems in Poland in the Years 1970–1985	160
MOLA Analysis and Repair of Damages in Precast Reinforced Concrete Panels	162
MÜSSIG Self-Supporting Structures for the Restoration of Balconies	164

**Session 6**

<b>Repair and Rehabilitation Methods of Historical Buildings</b>	<b>166</b>
<b>SOFRONIE</b>	
Innovative Method for Repairing Masonry Buildings	166
<b>GÜNTER, MÜLLER, HILSDORF</b>	
Investigation and Repair of Old Culturally Valuable Concrete Structures	168
<b>PAPIC, KLECINA, GULJAS</b>	
Evaluation and Preservation of Historic Buildings in Osijek	170
<b>MANDARA, MAZZOLANI</b>	
Confining of Masonry Walls with Steel Elements	172
<b>GROMYSZ</b>	
Repairs of Vertically Deflected Buildings	174
<b>PAKVOR, MURAVLJOV</b>	
Damages and Rehabilitation of the Orthodox Cathedral in Belgrade	176
<b>KAMINSKA, CZKWIANIANC, KOZICKI</b>	
Reconstruction of Wooden Floors in 19th Century Industrial Buildings	178
<b>VAN DER LINDEN, BLASS, SCHLAGER</b>	
Timber Floors Strengthened with Concrete	180
<b>GODYCKI-CWIRKO, PAWLICA</b>	
Construction and Design of Composite Concrete-Timber Floors	182
<b>SIGMUND, GULJAS, KLECINA</b>	
In-plane Stiffness of the Prussic Caps	184
<b>POPA</b>	
Consolidation Works for a Historic Building	186
<b>TAKAC, ZAGAR</b>	
Roof Structure Renewal of the St. Peter and Paul Church in Osijek	188
<b>ZEC</b>	
The Dynamic Buffer Zone System	190
<b>DREYER, HECHT</b>	
Injection Methods for Retrofitting of Moisture Damaged Constructions	192
<b>LOKOSEK, SIMUNIC BURSIC</b>	
Consolidation of the Church of St. Mihajlo near Ston	194
<b>PAJAK, SLUSAREK, KUBICA</b>	
Preservation of the State Oswiecim-Brzezinka Museum	196
<b>PAJAK, KUBICA, STAROSOLSKI</b>	
Repairs of Coal Processing Buildings under Continuing Production	198



BOSNJAK-KLECINA, HERMAN, SIGMUND Stress Analysis in Masonry Arch Structures	200
<b>Session 7</b>	
<b>Energy Saving and Building Physics</b>	202
STERNOVA Upgrading of Panel-Built Residential Houses	202
CZIESIELSKI Mold Fungus Formation in Large Panel Buildings and Subsequent Thermal Insulation	204
DREYER Thermal Protection and Moisture Proofing of Exterior Walls of Existing Buildings	206
KARIMIES, LEHTINEN, KETTUNEN, YRJÖLÄ Rain Screen Cladding Based on Steel Structures	208
VOGDT Rehabilitation of Large Panel Buildings using ETICS	210
GRZESZCZYK, WITCZAK Saving of Sacral Stained-Glass Window against Moisture Condensation	212
SIJANEC ZAVRL, GRUDEN Concept of Energy Restoration of Residential Buildings in Slovenia	214
CURTH Fully Automatic, Decentralised Ventilation System with Heat Recovery	216
TENNHARDT Complex Room Acoustics Analysis Methodology for Large Lecture Theatres	218
MARQUARDT Rehabilitation of Concrete Walls using Thermal Insulation	220
KASPER, KÄSER Mineral-Wool Based, Glased Curtain Walling with Solar Energy Use	222
ANDREICA, COMSA, RUS Influence of Glass Paned Areas on the Closing Walls of Buildings	224
SIJANEC ZAVRL, MALOVRH, ZUPAN Energy Audits of Schools in the Town of Kamnik	226
<b>Session 8</b>	
<b>Assessment and Rehabilitation of Existing Buildings after Accidents</b>	228
CRAINIC Seismic Rehabilitation of Existing Buildings in Romania	228





CROCI, BONCI War and Earthquake in Dubrovnik: Preventive and Remedial Measures	230
REEVES Load Testing of Large Panel System Dwellings	232
ZARNIC, BAUMGARTNER, BOSILJKOV Strengthening of Buildings according to Eurocode 8 and National Standards	234
SANDI Saving Buildings under Conditions of High Seismic Risk	236
DORKA, FLYGARE Earthquake Retrofit of Large Panel Buildings by Basement Isolation	238
DRITSOS, VANDOROS, TAYLOR Retrofitting of Reinforced Concrete Frame Buildings	240
CIONI, CROCE, SALVATORE Damage of Reinforced Concrete Structures Exposed to Violent Thermal Gradient	242
BUCUR, CHIVU, ARDELEA Repair and Rehabilitation – Three Case Studies in Bucharest	244
MARKOV, KOKOSHUEV, MARKOVA Analysis of Deterioration of Civil Buildings in South Ukraine	246
ANASTASESCU, GADEA Antiseismic Protection and Rehabilitation of Buildings in Timisoara	248
STRUFE Emergency Protection of War Damaged Buildings	250
KAWULOK Protection of Church Buildings on Mining Areas	252
SIECZKOWSKI, BIELAWSKI, DMOCHOWSKI Reinforcement of Apartment Buildings Exposed to Paraseismic Tremors	254
CATARIG, KOPENETZ, ALEXA Structural Assessment and Strengthening of Existing Buildings	256
SANDI, STANCU A Case Study on a Historical Monument and Methodological Implications	258
<b>IABSE REPORTS – RAPPORTS AIPC – IVBH BERICHTe</b>	<b>260</b>
CD-ROM Reference Numbers	266